HISTORIC AMERICAN ENGINEERING RECORD



INDEX TO PHOTOGRAPHS

HAER No. PA-242

Harbison-Walker Refractories Company West end of Shirley Street Mount Union Huntingdon County Pennsylvania

Jet Lowe, Photographer, May 1989

PA-242-1	GENERAL VIEW OF COMPLEX LOOKING NORTH FROM DRY GRIND BUILDING TO NO. 2 KILNS
PA-242-2	GENERAL VIEW OF COMPLEX LOOKING NORTHEAST FROM DRY GRIND BUILDING
PA-242-3	GENERAL VIEW OF COMPLEX LOOKING EAST FROM DRY GRIND BUILDING
PA-242-4	GENERAL VIEW OF COMPLEX LOOKING SOUTHEAST FROM DRY GRIND BUILDING
PA-242-5	GENERAL VIEW OF COMPLEX FROM TOP OF ELEVATOR BUILDING INTO ROTARY

HAER PA, 31-MTUN,

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

ADDENDUM TO
HARBISON-WALKER REFRACTORIES COMPANY
West end of Shirley Street
Mount Union
Huntingdon County
Pennsylvania

HAER No. PA-242 (P. 3)

PA-242-1 through PA-242-9 were previously transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jet Lowe, Photographer, May 1989

PA-242-10 (CT) VIEW SOUTH, SHOWING NO. 2 KILNS

HAER PA 31-MTUN,

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

ADDENDUM TO
HARBISON-WALKER REFRACTORIES COMPANY
West end of Shirley Street
Mount Union
Huntingdon County
Pennsylvania

HAER No. PA-242

(page 2)

Photographs PA-242-1 to PA-242-5 previously transmitted to the Library of Congress.

David Ames, Photographer, July 1991

PA-242-6 GENERAL VIEW LOOKING WEST FROM EASTERN EDGE OF COMPLEX. KILNS HAVE BEEN DEMOLISHED BUT KILN STACKS STILL STAND.

PA-242-7 GENERAL VIEW OF COMPLEX LOOKING NORTH THROUGH REMAINING KILN STACKS.

PA-242-8 GENERAL VIEW LOOKING NORTH.

PA-242-9 VIEW EAST FROM WESTERN EDGE OF COMPLEX. COLLAPSED OVERHEAD CONVEYOR IN FOREGROUND CARRIED GANISTER DOWN TO THE BRICKYARD FROM CRUSHING AND GRINDING FACILITY ON THE MOUNTAIN.